



SPAJANJE TRAKA

1. TOPLO SPAJANJE:



1. FINGER SPOJ



2. PREKLOPLJENI FINGER SPOJ




3. STEP SPOJ



2. MEHANIČKO SPAJANJE TRAKA (rastavljivi spoj)


Skice nekih tipova žičanih spojnica:

S tip
(AP tip, AM tip)




-spojnice na kartonu,
žica okruglog presjeka

A - tip



-spojnice na žici,
žica okruglog presjeka


G - tip




-polupločaste spojnice,
pravokutni presjek

Skice nekih tipova pločastih spojnica:

ALLIGATOR TIP SPOJNICE:




RS tip




ARJ tip

FLEXCO TIP SPOJNICE:



R2 tip



140 E
190 E

Kod mehaničkog spajanja bitno je naglasiti debljinu trake i minimalni promjer valjka.

